



調査日時：2013年8月12日 13:30~14:00  
場所：東京都板橋区  
外気温：36.0℃  
日射量：740W/m<sup>2</sup>  
撮影面：西面外壁



①日進産業東京支店 36.7℃



②ごみ集積所 40.0℃



③プレハブ 52.0℃



④マンション 45.5℃



⑤公衆トイレ 53.4℃




⑥プレハブ(緑のカーテン) 44.0℃




調査日時：2013年8月12日 13:30~14:00  
 場所：東京都板橋区  
 外気温：36.0°C  
 日射量：740W/m<sup>2</sup>  
 撮影面：西面外壁




①日進産業東京支店 36.7°C




②ごみ集積所 40.0°C




③プレハブ 52.0°C



④マンション 45.5°C



⑤公衆トイレ 53.4°C



⑥プレハブ(緑のカーテン) 44.0°C